

Contents

Chapter	Page
I. Properties of Glass	1
Soft glass and Pyrex. Expansion of glasses. Thermal behavior. Annealing. Devitrification.	
II. Flames and Torches.	7
Flame characteristics. Heating equipment. Bunsen burner. Meker burner. Initial heating. . Hand torches. Permanent torches or blast lamps Use of the torch. Cross-fires. Torches from glass.	
III. Equipment.	13
First aid; goggles. Stock glass. Distinguishing between glasses. Stoppers. Asbestos. Blow tube, swivel, and mouthpiece. Glass cutters. Grinding equipment. Carbons. Flaring tools. Forceps; beeswax. Flask holders. Rollers. The glass blower's bench.	
IV. Basic Operations.	23
Cutting glass. Cutting with hot cane. "Leading a crack." The hot-wire method. Cutting by blowing out. Rotation. Simultaneous rotation with both hands. Fire polishing. Flaring. "Squaring off." Bending. Nozzles; "pulling a point." Flanging. bomb tubes; temporary handles of cane. The hand torch. Melting-point tubes. Bulges. Temporary tubing handles. Blue glass as a practice aid.	
V. Blowing Involving One Piece of Glass.	36
Sealing a tube end. Blowing. Vial end. Bulb end. Bulb in the middle of a tube. Bends. Healing cracks.	
VI. End and T Seals.	42
End seals. Both tubes of same diameter. Rotation method. "Spotting" method. Tubes of different diameter. Cross-fires. T seals. Y tubes. "Suck" seals.	

Contents

Chapter	Page
VII. The Triple, Ring, or Inner Seal; The Dewar Seal. Supporting the glass. Planning the work. Flow trap. Method I. Braces. Method II. Method III. Method IV. Condensers. Exercises. Other traps. Ring seals through the side of a tube. Gas flowmeter. Dewar seal.	52
VIII. Use of the Hand Torch. Situations requiring hand torch. Both glass ends clamped. One end free. Closing a circuit. Sealing <i>in vacuo</i> . Special torches. High-vacuum leaks.	66
IX. Other Operations. Constrictions. Capillary. Capillary T seals. Sharp bends. Coils. Free-hand. Mandrel. Expansion bellows. Ground joints. Lubrication. Manipulation of ground joints. Grinding; refinishing. Rough grinding. Drilling. Marking glass. Solid glass. Stirrers. Viterous silica. Vycor. Seals. Bends. Graded seals. Devitrification.	71
X. Glass-To-Metal Seals. General principles; glass must wet metal. The oxide film. Thermal expansion. Platinum. Tungsten. Molybdenum. Kovar and Fernico. Pinch seals; Dumet. Housekeeper seals. Disc seal. Tubular seals. Solder seals; plantinizing. Iron, Chromium nickel. Porcelain.	87
XI. Finished-Equipment Exercises. "Anti-bumpers." Manometer-barometer. Vigreux column. Air condenser. Y cut-off. Melting-point bath. Glass aspirator. Double-surface condenser. McLeod gauges. Tipping McLeod. Calibration. Electrolysis cell. Diffusion or condensation pumps. Oil pump. Mercury pump. Pumping speed. Heaters. The pumping station.	100
Glossary.	119
Index.	127